



012

# CERTIFICATE OF REGISTRATION

This is to certify that

## **RW Joinery (Stockport) Ltd**

Mersey Street  
Stockport  
SK1 2HX

Meets the requirements of the Exova BM TRADA **Q-Mark Fire Door Manufacture** scheme to **STD 006 083 - Issue 2 - 11/07/2014**

**Karen Prendergast**  
Sector Director - Certification  
Exova BM TRADA

### Certificate Number

051

### Date of Initial Certification

12 January 2005

### Date of Last Issue

16 January 2017

### Date of Expiry

11 January 2020

Exova (UK) Ltd, (T/A Exova BM TRADA), Chiltern House, Stocking Lane, High Wycombe, Buckinghamshire, HP14 4ND, UK  
Registered Office: Exova (UK) Ltd, Lochend Industrial Estate, Newbridge, Midlothian EH28 8PL United Kingdom. Reg No. SC070429.

This certificate remains the property of Exova (UK) Ltd. This certificate and all copies or reproductions of the certificate shall be returned to Exova (UK) Ltd or destroyed if requested. Further clarification regarding the scope of this certificate and verification of the certificate is available through Exova BM TRADA or at the above address or at [www.exovabmtrada.com](http://www.exovabmtrada.com)

The use of the UKAS accreditation mark indicates accreditation in respect of those activities covered by the accreditation certification 012

Multisite clients - The scope of certification shown above includes the participating sites shown on the registration schedule

## Registration Schedule

### Branch

RW Joinery (Stockport) Ltd

### Address

Mersey Street  
Stockport  
SK1 2HX

### Scope

Assessment/ Test Report	Owner of Assessment/ Report	Doorset Description	Rating	Test Type
Chilt/A12151	Blankfort Inc.	Blankfort 30 Blankfort 30+	30min	BS476 Part 22
Chilt/A12152	Blankfort Inc.	Blankfort 60 Blankfort 60+	60min	BS476 Part 22
FEA/F99112A	Vicaima Ltd	FD30 – Flaxboard or chip core	30min	BS476 Part 22
Chilt/A13093	Vicaima Ltd	Vicaima Halspan 60 Doorsets	60min	BS476 Part 22
FEA/F97174	Halspan Limited	Prima 30 Prima Plus 30	30min	BS476 Part 22
FEA/F96103	Halspan Limited	Prima 60 Prima Plus 60	60min	BS476 Part 22
Chilt/A01204	Halspan Limited	Optima 30	30min	BS476 Part 22
Chilt/A01205	Halspan Limited	Optima 60	60min	BS476 Part 22
Chilt/A05151	Halspan Limited	Halspan 90	90min	BS476 Part 22
BMT/CNA/F15082	Halspan Limited	Halspan 120	120min	BS476 Part 22
Chilt/A13242	Sentry Panel products Ltd	Sentry Pro Tech 30 minute fire resisting doorsets	30min	BSEN 1634-1
Chilt/A13227	Sentry Panel products Ltd	Sentry Pro Tech 60 minute fire resisting doorsets	60min	BSEN 1634-1
FEA/F98164	Pacific Rim Wood Ltd	Flamebreak 30	30min	BS476 Part 22
FEA/F02141	Pacific Rim Wood Ltd	Flamebreak 60	60min	BS476 Part 22
Chilt/A02066	Falcon Panel Products	Strebord 44	30min	BS476 Part 22
Chilt/A02067	Falcon Panel Products	Strebord 54	60min	BS476 Part 22
Chilt/A13058	Moralt AG	LAMINESSE FireSafe and FireSmoke 44mm	30min	BS476 Part 22
Chilt/A13059	Moralt AG	LAMINESSE FireSafe and FireSmoke 54mm	60min	BS476 Part 22
Chilt/A13060	Moralt AG	LAMINESSE FireSound 54mm and 59mm	30min	BS476 Part 22
Chilt/A13060 Doorset B	Moralt AG	LAMINESSE FireSound 59mm	60min	BS476 Part 22
BMT/CNA/F14274	Moralt AG	LAMINESSE FireSound 44mm 30 minute Fire resisting doorsets incorporating Strebord 44 or Superpan door cores and STS	30min	BS476 Part 22
BMT/CNA/F15056	Sealed Tight Solutions Ltd	Intumescent seals and gaskets	30min	BS476 Part 22



BMT/CNA/F15057	Sealed Tight Solutions Ltd	60 minute Fire resisting doorsets incorporating Strebord 54 door cores and STS Intumescent seals and gaskets	60min	BS476 Part 22
BMT/CNA/F15058	Sealed Tight Solutions Ltd	Glazing seals and fire resistant hardware gaskets for 30 minute Fire Resisting Doorsets manufactured from proprietary door cores (See note*)	30min	BS476 Part 22
BMT/CNA/F15058	Sealed Tight Solutions Ltd	Glazing seals and fire resistant hardware gaskets for 60 minute Fire Resisting Doorsets manufactured from proprietary door cores (See note*)	60min	BS476 Part 22
BMT/CNA/F15120	Sealed Tight Solutions Ltd	30 minute Fire resisting doorsets incorporating Halspan Prima 30 and Halspan Optima 30 door cores and STS Intumescent seals and gaskets	30min	BS476 Part 22
BMT/CNA/F15121	Sealed Tight Solutions Ltd	60 minute Fire resisting doorsets incorporating Halspan Prima 60 and Halspan Optima 60 door cores and STS Intumescent seals and gaskets	60min	BS476 Part 22
BMT/CAN/F15259	Sealed Tight Solutions Ltd	30 minute Fire Resisting Doorsets incorporating Vicaima SDC & HDC door leaves and STS Intumescent seals and gaskets	30min	BS476 Part 22